


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan/95 To (mo./yr.) Jan/96
 2. DOGM File Number (Mine No): M / 045 / 027
 3. Mine Name: ROUDABUSH
 4. Mineral(s) Mined (or permitted to mine): SILICA ROCK
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
SW 1/4, SW 1/4, Section 14, Township 45, Range 6W
NW 1/4, NW 1/4, Section 23, Township 45, Range 6W
1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: A.P. GREEN REFRACTORIES INC.
 8. Permanent Street Address : Green Boulevard
City, State, Zip: Mexico, MO 65265
Phone: 573-473-3626
 9. Company Representative (or designated operator):
Name: CHARLES E. STACK
Title: MGR., MINING & RAW MATERIAL OPERATIONS
Business Address: GREEN BOULEVARD
City, State, Zip: MEXICO, MO 65265
Phone: 573-473-3302
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 40,000 TONS

3. How much **additional acreage** was disturbed during the past year? 0.65
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
ONE ADDITIONAL CUT APPROXIMATELY 60' WIDE AND 400' LONG WAS DRILLED,
BLASTED AND CRUSHED DURING 1995. THE CUT WAS LOCATED EAST OF THE
SOUTH END OF THE PREVIOUS HIGHWALL. AVERAGE DEPTH OF CUT WAS 25'.
5. How much acreage was **reclaimed** during the past year? 0
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
THE FINE (-3/4") MATERIAL FROM THE CRUSHING/SCREENING OPERATION
WAS STORED IN THE PREVIOUSLY MINED AREA.
7. What is the total disturbed acreage at years end? 5.75
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
NO MINING/RECLAMATION IS PLANNED FOR 1996. USAGE WILL BE FROM
EXISTING STOCKPILES.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

CHARLES E. STACK

Title of Operator:

MGR., MINING & RAW MATERIAL OPERATIONS

Signature of Operator:


Charles E. Stack

Date:

JANUARY 2, 1996



January 12, 1996



State of Utah
DNR, Div. of Oil, Gas & Mining
355 W. North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Dear Sir:

RE: Annual Report for Year 1995
Roudabush Mine #1
M/045/027

Enclosed is the Annual Report of Mining Operation for 1995. The location of the area mined during 1995 is shown on a map attached to the report. The resulting highwall was reduced in total height by mining an area approximately 25 feet in thickness.

If you have any questions or require additional information, please let me know.

Sincerely,

Charles E. Stack
Mgr., Mining & Raw Material Operations

mb

enclosure

cc: O. Hunter

MH:\STACK\UTAH\ROUDABUS.016